CORRES. CONTROL INCOMING LTR NO.			
1461 RF93	Department of Energy		
DUE	ROCKY FLATS OFFICE P.O. BOX 928		
DATE	GOLDEN, COLORADO 80-402-0928		
DIST. LTR ENC BENEDETTI, R.L.			
BERMAN, H.S.	MAR 25 1993	93-DOE	-03633
CARNIVAL.G.J. CORDOVA, R.C. CROUCHER, D.W.			
DAVIS, J.G. FERRERA, D.W. HANNI, B.J.	Mr. Martin Hestmark U. S. Environmental Protection Agency, Region VIII	O	
HEALY, T.J. HEDAHL, T.G. HILBIG, J.G.	ATTN: Rocky Flats Project Manager, 8HWM-RI 999 18th Street, Suite 500, 8WM-C	ROCKI CORROCKI	lin 2
IDEKER, E.H. KIRBY, W.A.	Denver, Colorado 30202-2405	22 4.7e	=
KUESTER, A.W. LEE, E.M. MANN, H.P.	Mr. Gary Baughman Hazardous Waste Facilities Unit Leader	2 mg 2	68
MARX, G.E. McKENNA, F.G. MORGAN, R.V.	Colorado Department of Health 4300 Cherry Creek Drive South		Self-cod by Self-cod-cod Self-cod-cod
POTTER, G.L. RILEY, J.H.	Denver, Colorado 80222-1530	<u> </u>	Ü
SANDLIN, N.B. SATTERWHITE, D.G SCHUBERT, A.L.	Gentlemen:		
SETLOCK, G.H. SHEPLER, R. L.	This letter is to inform you that the exact location of a borehole in IHSS 1 been changed from the location approved by EPA and CDH in Technical		
SULLIVAN, M.T. SWANSON, E.R. WILKINSON, R.B.	(TM7), Soil Boring Sampling Plan-Ash Pits, Incinerator and Concrete Wa approval of TM7, the exact location of the boring as stated in the TM was	sh Pad. [Jpon
WILSON, J.M. ZANE, J.O.	directly under a north-south 115 kv power line. The borehole has been relapproximately 30 feet west and slightly north of the original location (see	located	
arat MX	but is still well within the 133.5 IHSS boundary. The change in location f should have no impact on the data objectives for this IHSS.		
	If you have any questions, please contact Jen Pepe of my staff at 966-2184	1 .	
	Sincerely,		
Taylor			
	James K. Hartman Assistant Manager for Transiti	O n	
CORRES CONTROL X X TRAFFIC	and Environmental Restoration		
Reviewed for Addressee Corres. Control RFP	cc: A. Rampertaap, EM-453		
32693	B. Lavelle, EPA J. Shieffelin, CDH	e	
DATE BY	M. Amdt, EG&G		
Ref Ltr. #	¥		